

# **EXHIBIT 43**

CADETAIL

ISSUE	case_id	created_orVin	series_name
-------	---------	---------------	-------------

OTHER	K2873727	1/20/2015 KNDPCCA66B7	SPORTAGE
-------	----------	-----------------------	----------

CADETAIL

series\_year

2011

CADETAIL

history

\*\*\* NOTES 01/20/2015 01:10 PM US Mountain Standard Time CWilliams Action Type:Manager review  
Dispatching to NCA

1. service manager called in and stated sunroof shattered while driving
2. possible product liability case
3. please review the case and contact the customer and dealership accordingly

\*\*\* PHONE LOG 01/21/2015 02:23 PM Pacific Daylight Time SMarino Action Type:Outgoing call  
Called dealer, CA224 - spoke to Dominick, service mgr

1. Reviewed case with Dominick
2. Requested pictures

\*\*\* PHONE LOG 01/22/2015 08:20 AM Pacific Daylight Time SMarino Action Type:Outgoing call

\*\*\* PHONE LOG 01/22/2015 08:24 AM Pacific Daylight Time SMarino Action Type:Outgoing call  
Called dealer, CA224 - Spoke to Dominick

1. Writer requested pictures

\*\*\* NOTES 01/22/2015 11:32 AM Pacific Daylight Time SMarino Action Type:Dealer contact  
Received email - pictures reviewed

Sent email to Dominick Mongelli , service mgr @ CA224

1. After reviewing pictures: there is not any obvious sings of cause of the sunroof shatter, either due to external impact or not.
2. Advised KMA has authorized replacement of the sunroof as a one-time good will gesture on the behalf of the customer.

\*\*\* PHONE LOG 01/22/2015 11:45 AM Pacific Daylight Time SMarino Action Type:Outgoing call  
Called dealer, CA224 - Spoke to Dominick

1. Writer advised on payment process

CADETAIL

MDL	MY	MDL_CD	DATE_MFG	DATE_WHL	DATE_TIS	PROJ
-----	----	--------	----------	----------	----------	------

CADETAIL

RTL_YR	MCD_OPT	CD_ACC	DLR	DLRNAME	ST
--------	---------	--------	-----	---------	----

CADETAIL

da	ISSU PFP	WEEK
----	----------	------

1/18/2015